

**Easement Holders Properties Marked During The
Hazard Tree Patrol For The SV of Sundance Beach
September 2014**

| Adjacent Lot No. | Name | No. of Removals | Description of trees/work | Action required | Priority 1=critical (Orange) 2=moderate (Pink) 3=not urgent (Purple) | Priority Flagging Color | Comments |
|------------------|------------------|-----------------|---|----------------------|--|-------------------------------|-------------------------------|
| 5 | Lesko | 3 | 1 Aspen with heavy lean toward rd., 1 dead Aspen, 1 Balsam with broken top and In decline. | Remove | 2,3 | Pink and Purple | |
| 11 | Boswell/SV | 1 | Birch in decline from top down | Remove | 1 | Orange | |
| 16 | Herbers | 2 | Birches with bark inclusion and butt/root rot (Monitor other Birches) | Remove | 3 | Purple | |
| 16/17 | Herbers/McDonald | 1 | Balsam with butt/root rot | Remove | 2 | Pink | |
| 19 | Hunter | 1 | 1 Aspen with Hypoxylon Canker and dead top | Remove | 3 | Purple | Add on 2015 |
| 21 | Munn | 4 | Previously topped Balsams | Remove | 3 | Purple | |
| 31 | Schumacher | 1 | Previously topped Balsam in decline from the top down | Remove | 2 | Pink | |
| 32 | French | 1 | Birch with dead top | Remove | 2 | Pink | |
| 45 | McKenzie | 1 | Previously topped Balsam leaning to the east | Remove | 1 | Orange | |
| Hall | SV | 11 | Approx.' 11 trees (Balsam & Aspen) | Remove | 1,2 | Pink | Marked with PUL's |
| 54/55 | McKinnon/Klotz | 1 | 1 Aspen dead behind shed | Remove | 2 | Pink | Add on 2015 |
| 55 | Klotz | 1 | Birch in decline leaning over dock/lake | Remove | 2 | | Complete |
| 56 | Dawson | 1 | Dead Aspen | Remove | 1 | | Complete |
| 62 | Branton | 3 | Balsam poplar with catfacing on the tension side and leaning toward lake/dock | Remove | 2 | Pink | |
| 67 | Sirois | 1 | Large leaning birch | Prune and monitor | 3 | Purple | |
| 74 | Waterhouse | 4 | 4 Previously Topped Balsam Poplars | Remove | 2 | Pink | Owner of tree corrected |
| 75 | Jenkinson | 3 | 3 of 4 Green Ash. | Remove | 2 | | Trimming Complete |
| 76 | Kenway | 1 | Balsam with broken top | Monitor | 3 | N/A | Not Flagged |
| 77 | Thompson | 1 | Large catfaced Balsam leaning toward road | Prune or remove | 2 | Pink | |

| | | | | | | | |
|-------|------------------|---|--|--------|-----|-----------------|----------------|
| 85 | Lang | 1 | Aspen with dead top | Remove | 2 | Pink | |
| 88/89 | Crough/Ariss | 2 | Small dead Aspen (hypoxolon canker) & a dead Balsam Poplar | Remove | 2 | Pink | One tree added |
| 89 | Ariss | 1 | Aspen in decline from top down | Remove | 1 | Orange | |
| 97 | Hiller | 1 | Aspen in decline from top down | Remove | 1 | Orange | |
| 97/98 | Hiller/Humphries | 1 | Balsam in decline from top down | Remove | 1 | Orange | |
| 99 | Miller | 1 | Balsam in decline from top down | Remove | 1 | | Complete |
| 100 | Asselin | 2 | 1 dead Aspen & 1 balsam in decline | Remove | 1 | | Complete |
| 102 | Fjell | 2 | 1 previously topped Aspen with hypoxolon canker. 1 Balsam with butt/root rot | Remove | 3,1 | Orange & Purple | |
| 105 | Andraschko | 1 | Pine with needle cast | Remove | 3 | Purple | |
| 108 | McDonald | 4 | Balsam with dead tops, one with butt/root rot | Remove | 1 | Orange | One tree added |
| 109 | Trent | 6 | Aspen with hypoxolon canker and wood pecker holes | Remove | 1 | Orange | |

Hazard Tree Patrol SV of Sundance Beach
September 2014

| Adjacent Lot No. | Name | No. of Removals | Description of trees/work |
|------------------|---------------------|-----------------|--|
| 5 | Lesko | 3 | 1 Aspen with heavy lean toward rd., 1 dead Aspen, 1 Balsam with broken top and in decline. |
| 11 | Boswell/SV | 1 | Birch in decline from top down |
| 12 | Fitzgerald | 2 | 1 dead Aspen, 1 large catface Aspen leaning toward lake |
| 16 | Herbers | 2 | Birches with bark inclusion and butt/root rot |
| 16/17 | Herbers/McDonald | 1 | Balsam with butt/root rot |
| 21 | Munn | 4 | Previously topped Balsams |
| 24 | Brown/SV | 2 | 1 dead Aspen, 1 Aspen in decline by lake shore |
| 31 | Schumacher | 1 | Previously topped Balsam in decline from the top down |
| 32 | French | 1 | Birch with dead top |
| 45 | McKenzie | 1 | Previously topped Balsam leaning to the east |
| Hall | SV | 11 | Approx' 11 trees (Balsam & Aspen) |
| 55 | Klotz | 1 | Birch in decline leaning over dock/lake |
| 56 | Dawson | 1 | Dead Aspen |
| 62 | Branton | 3 | Balsam poplar with catfacing on the tension side and leaning toward lake/dock |
| 64 | Roy/SV | 1 | Balsam in decline from top down beside 65's retaining wall |
| 67 | Sirois | 1 | Large leaning birch |
| 70/71 | Gokiert/Kirstien/SV | 5 | Previously topped poplars on PUL |
| 75 | Jenkinson | 3 | 3 of 4 Green Ash |
| 76 | Kenway | 1 | Balsam with broken top |
| 77 | Thompson | 1 | Large catfaced Balsam leaning toward road |
| 85 | Lang | 1 | Aspen with dead top |
| 86 | Fletcher/SV | 1 | Balsam leaning over dock |
| 87 | Gardiner/SV | 2 | Aspen by tire swing + one with large limb removed and in decline |
| 88/89 | Crough/Ariss | 1 | Small dead Aspen (hypoxylon canker) |
| 89 | Ariss | 1 | Aspen in decline from top down |
| 95/96 | Falkenberg/Read/SV | 4 | 2 previously topped Aspen stumps with hypoxylon canker, 2 previously topped Balsam with co-dominant tops |
| 97 | Hiller | 1 | Aspen in decline from top down |
| 97/98 | Hiller/Humphries | 1 | Balsam in decline from top down |
| 99 | Miller | 1 | Balsam in decline from top down |
| 100 | Asselin | 2 | 1 dead Aspen & 1 balsam in decline |
| 102 | Fjell | 2 | 1 previously topped Aspen with hypoxylon canker. 1 Balsam with butt/root rot |
| 103/104 | Harris/Prochnau/SV | 3 | 1 dead Birch, 2 Aspen with hypoxylon canker |
| 105 | Andraschlo | 1 | Pine with needle cast |
| 108 | McDonald | 3 | Balsam with dead tops, one with butt/root rot |
| 109 | Trent | 6 | Aspen with hypoxylon canker and wood pecker holes |
| 110/113 | Armand/Ginter/SV | 4 | 3 Aspen, 1 by dock, dead or in decline |